



“Sigma” (Standard deviation) is a measure of variation.

“Sigma” is a measure of variation.

Plus or minus one standard deviation around the mean is about 68% of the total process output.

Standard deviation

Standard deviation 68%

What does “Six Sigma” mean?

“Six Sigma”

How can we achieve Six Sigma?

Standard deviation

Note: Long term variation statistics used (with $\pm 1.5s$ shift)

Standard deviation $\pm 1.5s$

Benchmarking

Standard deviation

Cost of Poor Quality as a % of revenue

Standard deviation

Our Services

-  Document Translation Services
-  Interpretation Services
-  Desktop Publishing Services
-  Video Translation Solutions